



# LONG-TERM PERFORMANCE AND RELIABILITY ASSESSMENT OF 8 PV ARRAYS AT SANDIA NATIONAL LABORATORIES

Jennifer E Granata, William E Boyson, Jay A Kratochvil,  
and Michael A Quintana

Sandia National Laboratories

Presented at the 34<sup>th</sup> IEEE PVSC

June 11, 2009

Philadelphia, PA



Sandia is a multiprogram laboratory operated by Sandia Corporation, a Lockheed Martin Company,  
for the United States Department of Energy's National Nuclear Security Administration  
under contract DE-AC04-94AL85000.





# ACKNOWLEDGEMENTS

- Sandia acknowledges the support of the DOE Solar Energy Technologies Program in particular for the work presented here.



# OUTLINE

- Motivation
- Background
- Array field overview
- Test method
- Initial data
- Trouble-shooting the arrays
- Summary



## MOTIVATION

- Use Sandia's 95 kW array field to understand:
  - System-level performance degradation
  - System-level reliability issues seen in the field
  - Operations and Maintenance
- Apply a process to assess each of these in this “microcosm” of a larger, multi-array, multi-inverter system
- Transfer knowledge to PV community



## BACKGROUND

- Sandia's Solar Energy Systems team brings a *systems approach* to PV performance, degradation and reliability
  - The PV Systems Evaluation Lab (PSEL) focuses on module issues and how they fit into a system
  - The Distributed Energy Technologies Lab (DETL) focuses on inverters and the balance-of-systems aspects
  - Working together provides AC and DC expertise for most aspects of PV systems



## Array Field Overview

- DETL array field used primarily to assess *fielded* performance and reliability of inverters
  - DETL array field currently uses ~95 kW (STC) from 9 different systems
  - Strings are reconfigurable to test various inverter sizes and configurations
  - All but one system at fixed latitude tilt
- PSEL performs initial DC “acceptance test” and periodic DC performance assessments on arrays



# Array Field Overview

Array #	Tech	Strings	Modules /String	Instl. Date	Name Plate Rating (kW)
1	a-Si	70	1	2002	3.06
2	c-Si	4	20	2004	6.00
3	mc-Si	4	22	2005	7.04
4	mc-Si	4	22	2005	7.04
5	c-Si	6	7	2005	9.31
6	c-Si	3	28	2005	7.04
7	a-Si	3	2	2006	3.26
8	c-Si	3	21	2006	7.92
9	c-Si	24	12	2008	50.50

***Primary focus of this presentation:***  
**Six silicon-based PV arrays at Sandia's DETL**






## Array DC Test Method

- 2-3 modules baselined prior to installation
  - Full outdoor electrical performance testing and thermal response on a tracker and indoor dark IV
  - Analyzed according to Sandia PV Performance Model
- DC string-level testing
  - Thermocouples on backside of two modules per array
  - Measured during spring or autumn: solar incident angles  $< 50$  degrees during AMa 1.5
  - Two c-Si reference cells at POA to measure irradiance and soiling effects
  - Daystar data acquisition system and thermocouple data logger to gather data
  - Collect IV curves and temp data every 2 minutes over a mostly clear sky day
  - Estimated measurement error is  $\pm 2.5\%$




# Array DC Test Method

- Periodic DC performance assessments on arrays
  - Date of re-measure for this assessment: October 2008
  - Same method used as outlined for DC performance after disconnecting from inverter



Illumination and module temperature during October 2008 testing



Effect of soiling on arrays  
*Included in data translation to SRC*

# Array Performance Change

Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #1, a-Si, 3.06 kW Installed 2002	% diff*	<b>-45.3</b>	<b>-45.9</b>	<b>-4.4</b>	<b>-3.6</b>	<b>-47.9</b>	<b>-0.4</b>
	%/year	<b>-7.0</b>	<b>-7.1</b>	<b>-0.7</b>	<b>-0.6</b>	<b>-7.4</b>	<b>-0.1</b>
System #2, mc-Si, 5.42 kW Installed 2004	% diff	<b>+2.1</b>	<b>+1.5</b>	<b>-0.9</b>	<b>-2.1</b>	<b>-0.7</b>	<b>-1.8</b>
	%/year	<b>+0.5</b>	<b>+0.4</b>	<b>-0.2</b>	<b>-0.5</b>	<b>-0.2</b>	<b>-0.4</b>
System #3, mc-Si, 6.87 kW Installed 2005	% diff	<b>-24.6</b>	<b>-24.9</b>	<b>-2.2</b>	<b>-1.0</b>	<b>-25.6</b>	<b>+1.0</b>
	%/year	<b>-8.0</b>	<b>-8.1</b>	<b>-0.7</b>	<b>-0.3</b>	<b>-8.3</b>	<b>+0.3</b>
System #4, mc-Si, 7.00 kW Installed 2005	% diff	<b>-1.9</b>	<b>-1.8</b>	<b>+0.9</b>	<b>+0.6</b>	<b>-1.2</b>	<b>-0.1</b>
	%/year	<b>-0.6</b>	<b>-0.6</b>	<b>+0.3</b>	<b>+0.2</b>	<b>-0.4</b>	<b>-0.0</b>
System #5, mc-Si, 7.99 kW Installed 2005	% diff	<b>-17.2</b>	<b>-16.7</b>	<b>-0.2</b>	<b>-0.3</b>	<b>-17.0</b>	<b>+0.6</b>
	%/year	<b>-5.6</b>	<b>-5.4</b>	<b>-0.1</b>	<b>-0.1</b>	<b>-5.5</b>	<b>+0.2</b>
System #6, mc-Si, 6.93 kW Installed 2005	% diff	<b>-0.3</b>	<b>-2.0</b>	<b>-0.1</b>	<b>-2.3</b>	<b>-4.3</b>	<b>-3.8</b>
	%/year	<b>-0.1</b>	<b>-0.7</b>	<b>-0.0</b>	<b>-0.8</b>	<b>-1.4</b>	<b>-1.3</b>
System #7, a-Si, 3.26 kW Installed 2006 (Roof mount)	% diff*	<b>-2.6</b>	<b>+0.4</b>	<b>-1.0</b>	<b>+0.3</b>	<b>+0.9</b>	<b>+4.3</b>
	%/year	<b>-1.2</b>	<b>+0.2</b>	<b>-0.5</b>	<b>+0.1</b>	<b>+0.4</b>	<b>+2.0</b>
System #8, c-Si, 5.69 kW Installed 2006	% diff	<b>-1.1</b>	<b>-9.8</b>	<b>+0.4</b>	<b>+3.3</b>	<b>-6.9</b>	<b>-6.2</b>
	%/year	<b>-0.5</b>	<b>-4.9</b>	<b>+0.2</b>	<b>+1.6</b>	<b>-3.5</b>	<b>-3.1</b>

% difference calculated from initial measured data or from Name Plate\*



## A-Si Systems: #1, #7

- A-Si System #1: Nothing of interest to be learned
  - Older technology, known to degrade quickly
  - No longer being manufactured
- A-Si system #7: Behaving as expected
  - Not tested upon installation
  - First DC test October 2008
  - Has reached the name plate values to within measurement error after 2.5 years in the field
  - A-Si stabilization expected within the first year
    - No additional degradation is being observed in the early years for this system

Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #1, a-Si, 3.06 kW Installed 2002	% diff	-45.3	-45.9	-4.4	-3.6	-47.9	-0.4
	%/year	-7.0	-7.1	-0.7	-0.6	-7.4	-0.1
System #7, a-Si, 3.26 kW Installed 2006 (Roof mount)	% diff	-2.6	+0.4	-1.0	+0.3	+0.9	+4.3
	%/year	-1.2	+0.2	-0.5	+0.1	+0.4	+2.0

*Note data is not corrected for a-Si seasonal effects*



## Systems #2, #4 and #6

- System #2, c-Si: Behaving as expected
  - Oldest of the crystalline silicon systems, installed mid 2004
  - Demonstrated consistent performance over nearly five years in the field, with no measurable change in parameters
- Systems #4 (mc-Si) and #6 (c-Si): Behaving as expected
  - Both installed in October 2005
  - Showing little to no degradation within measurement error

Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #2, mc-Si, 5.42 kW Installed 2004	% diff	+2.1	+1.5	-0.9	-2.1	-0.7	-1.8
	%/year	+0.5	+0.4	-0.2	-0.5	-0.2	-0.4
System #4, mc-Si, 7.00 kW Installed 2005	% diff	-1.9	-1.8	+0.9	+0.6	-1.2	-0.1
	%/year	-0.6	-0.6	+0.3	+0.2	-0.4	-0.0
System #6, mc-Si, 6.93 kW Installed 2005	% diff	-0.3	-2.0	-0.1	-2.3	-4.3	-3.8
	%/year	-0.1	-0.7	-0.0	-0.8	-1.4	-1.3



## System #3, mc-Si

- System #3, mc-Si: One failed module = 25% power loss
  - System #3 demonstrated much greater losses than expected
  - A 4-string module, 25% power and current loss was likely due to one lost string
  - Trouble-shooting included:
    - Visual Inspection
    - Fuse and Interconnect check
    - IR Imaging in the field
    - Module-by-module Voc and IV check


Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #3, mc-Si, 6.87 kW	% diff	-24.6	-24.9	-2.2	-1.0	-25.6	+1.0
Installed 2005	%/year	-8.0	-8.1	-0.7	-0.3	-8.3	+0.3




## System #3, mc-Si

- Trouble-shooting results:
  - Visual Inspection showed no cracked or discolored modules
  - All fuses and interconnects operating
  - All strings hooked up correctly
  - No obvious lost modules under IR Imaging in the field
  - All modules operative based on module-by-module Voc check
  - Found one intermittent module under module-by-module IV sweep in the field

*Sample IR images in the field*




*IR images in the field with issues observed; module on left intermittent*





## System #3, mc-Si



- Assess intermittent (“IM”) module:
  - Dark IV performed on “IM” module and on a companion module from the array
  - No major differences in performance, other than intermittency and difficulty reaching high voltage





## System #3, mc-Si

- Assess intermittent (“IM”) module:
  - Outdoor performance on “IM” module and on a companion module from the array
  - Companion module performed as expected
  - “IM” module had complete drop-outs unrelated to time, temperature, or illumination level
  - No major differences in performance, other than intermittency





## System #3, mc-Si

- Assess intermittent (“IM”) module:
  - It was possible to induce the intermittency by manipulating the pigtailed, suggesting the failure mechanism is in the attachment of the pigtail to the circuit.
  - Remaining steps to prove this hypothesis include:
    - Non-destructive imaging techniques of the module to look for damage
    - Take the junction box apart
- DC test repeated in February 2009 after replacing intermittent module
  - Recovered to within measurement error of initial test

Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #3, mc-Si, 6.87 kW 3 year Assessment	% diff	<b>-24.6</b>	<b>-24.9</b>	<b>-2.2</b>	<b>-1.0</b>	<b>-25.6</b>	<b>+1.0</b>
	%/year	<b>-8.0</b>	<b>-8.1</b>	<b>-0.7</b>	<b>-0.3</b>	<b>-8.3</b>	<b>+0.3</b>
Retest after module replacement	% diff	<b>+0.6</b>	<b>+0.3</b>	<b>+1.4</b>	<b>+1.8</b>	<b>+2.0</b>	<b>+0.0</b>
	%/year	<b>+0.2</b>	<b>+0.1</b>	<b>+0.5</b>	<b>+0.6</b>	<b>+0.7</b>	<b>+0.0</b>



## System #5, c-Si

- System #5, c-Si: Loss due to Balance-of-Systems Error
  - System #5 demonstrated much greater losses than expected
  - A 6-string module, 17% power and current loss was likely due to one lost string
  - Trouble-shooting included:
    - Visual Inspection
    - Fuse and Interconnect check
    - IR Imaging in the field
    - Module-by-module Voc and IV check

Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #5, mc-Si, 7.99 kW Installed 2005	% diff	-17.2	-16.7	-0.2	-0.3	-17.0	+0.6
	%/year	-5.6	-5.4	-0.1	-0.1	-5.5	+0.2



## System #5, c-Si

- Trouble-shooting results:
  - Visual Inspection showed no cracked or discolored modules
  - All fuses and interconnects operating
  - No stand-outs under IR Imaging in the field
  - All modules operative based on module-by-module Voc check
  - String-level hookup check revealed 6<sup>th</sup> string connected incorrectly
    - Corrected string hookup
  - DC test repeated in February 2009
    - Recovered to within measurement error of initial test

Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #5, mc-Si, 7.99 kW 3 year Assessment	% diff	-17.2	-16.7	-0.2	-0.3	-17.0	+0.6
	%/year	-5.6	-5.4	-0.1	-0.1	-5.5	+0.2
Retest after string polarity change	% diff	-0.6	+0.0	+0.3	-0.3	-0.3	+0.1
	%/year	-0.2	+0.0	+0.1	-0.1	-0.1	+0.0



## System #8, c-Si

- System #8, c-Si: Loss due to Balance-of-Systems Error
  - System #8 technology requires positively-grounded inverter for optimal performance
  - Quick check found it was hooked to a negatively-grounded inverter
  - DC test repeated after one week on correct inverter
    - Recovered from 34% power loss to 7% power loss
  - DC test repeated in February 2009 after 4 months on correct inverter
    - Recovered to within measurement error of initial test

Array	Test Date	Isc [A]	Imp [A]	Voc [V]	Vmp [V]	Pmp [W]	FF
System #8, c-Si, 5.69 kW 2 year Assessment	% diff	-1.1	-9.8	+0.4	+3.3	-6.9	-6.2
	%/year	-0.5	-4.9	+0.2	+1.6	-3.5	-3.1
Retest after 4 months on +grounded inverter	% diff	-3.7	-3.7	+1.6	+1.2	-2.5	-0.3
	%/year	-1.8	-1.8	+0.8	+0.6	-1.2	-0.1



## RELIABILITY

- The fielded arrays were examined for reliability issues and/or potential for failure. The following are issues observed in modules that contribute to reduced reliability:
  - Performance loss  $>1\%$  per year
  - Encapsulant/backsheet discoloration (2 c-Si technologies)
  - Burn marks/arcing (2 c-Si technologies)
  - Backsheet delamination visible under visual inspection
  - Hot spots seen in IR images
  - Broken glass
  - Breakdown in polymer outer sheet
  - Corrosion of interconnect regions



# RELIABILITY

- Of the reliability issues discovered, some are easily classified as failures, others may be considered failures based on aesthetics, and some are indicators of likely premature failure
- There is still too little data for statistical reliability assessments on these arrays
- The issues observed will be followed in coming years, particularly to look for early indicators of module failure




## Next Steps

1. Additional failure analysis of IM module from System #3
2. Investigate the AC data to look for patterns and early indicators of degradation
3. Remeasure modules from each system on the 2-axis tracker to document any module-level degradation
4. Further investigation of data trends for degradation beyond measurement error
5. Annual or bi-annual DC testing on each system to continue monitoring any long term degradation and follow progression of noted reliability concerns



## Next Steps

- Further investigation of data trends for degradation beyond measurement error
- Normalized power versus time after restoring arrays shows likely true power degradation in System #6 and possibly System #4





## Conclusions and Lessons Learned

- Only System #6 showed true power degradation beyond experimental error at  $4.3\% \pm 2.5\%$ , (ave.  $1.4\% \pm 0.8\%$ /year)
- In all other cases, the degradation rate was less than the experimental error
- Lessons learned:
  - Proper commissioning is essential to detect installation errors
  - Acceptance testing should also be performed following any maintenance work
    - Testing and checking against expected array output would have quickly caught loss mechanisms for Systems #5 and #8
  - Sufficiently sensitive string-level monitoring might have detected the string degradation due to failed module in System #3
  - Peer to peer (string to string) monitoring at the string level would have certainly detected string degradation due to the failed module



## Contact Information

Thank You!

Contact Information:

Jennifer Granata

[jegrana@sandia.gov](mailto:jegrana@sandia.gov)

505 844 8813