

# Lightning exposure of wind turbines: Field measurements and implications in the LPS design and service strategies

Javier López, Stephan Vogel, Lisa Carloni, Søren F. Madsen Polytech A/S R&D, Electrical and Mechanical, Advanced Engineering and Simulation Albuquerque, NM – 2024-09-18



#### Agenda

- Lightning exposure:
  - Field measurements.
  - Accumulated exposure.
- Implications in Blade LPS design and service:
  - Understanding the risk.
  - LPS design.
  - LPS Inspection and Service
- 360° Lightning Protection



## Lightning exposure



- Lightning dataset:
  - LKDS lightning current sensors in all blades. Rogowski coil based.
  - 1.5s recorded per strike with a resolution of 0.1µs.
  - Discrimination and analysis of all strokes within the strike.
  - Parameters defined in IEC standard measured:
    - Ipeak [kA], Q [C], AI [kJ/Ω].
    - Waveform steepness [kA/µs].
- Weather dataset: ERA5 reanalysis dataset.







- Main focus on two onshore sites (1000 2000 m ASL, site dependent).
- Observation period: November 2021 May 2024.
- 501 lightning strikes detected on Site 1.
- 2489 lightning strikes detected on Site 2.
- Site 2 is ~1000m lower than Site 1.
- Lightning type distribution:

5x more strikes on Site 2

	Downward lightning	Upward lightning
Site 1	22%	78%
Site 2	18%	82%

\* For comparison of the lightning type distribution, other sites are considered, although the size of the datasets does not allow using them to obtain accurate conclusions of lightning parameters.



- Reasons for the large number of upward lightning:
  - Height of the tall structures + location at elevated terrain.
  - Weather conditions.
- Warm weather-type storms:
  - Clouds develop vertically and are located high above ground: large distance to the wind turbines leads to a more even distribution of electric field and a larger number of naturally-produced downward lightning.
  - Downward lightning can trigger upward lightning from nearby structures.
- Cold weather-type storms:
  - Shallower clouds locate close to ground: the short distance (even 0 distance) to the wind turbines leads to an uneven distribution of electric field that exposes more the turbines that are in the direction of approach of the charged clouds.
  - Downward lightning occurs spontaneously under the presence of the clouds.



Yuan, Shanfeng et al. "Characteristics of Upward Lightning on the Beijing 325m Meteorology Tower and Corresponding Thunderstorm Conditions." Journal of Geophysical Research-atmospheres 122.22 (2017): 12093-12105. Web.







#### Field measurements – Accumulated exposure

- Lightning parameters measured and how they compare to IEC parameters.
- Maximum and accumulated parameters according to the IEC testing requirements:
  - Maximum peak current in a single strike = 200 kA.
  - Long stroke charge threshold = 300 C.
  - Maximum accumulated charge =
    - 900C in an accumulated exposure test.
    - 2700C in a winter lightning accumulated exposure test.
  - Maximum specific energy in a single strike =  $10 \text{ MJ}/\Omega$ .
- In terms of exposure, for charge related damages, accumulated values can be more relevant than the number of strikes exceeding parameters.
- Inspection and maintenance must be driven by the exposure, and not by a calendar





#### ~1000C



#### ~2500C



#### Site 1 – Charge accumulation



19% of the blades exceed the 900C charge threshold.

Polytech

Wind for life<sup>T</sup>

#### Site 2 – Charge accumulation



61% of the blades exceed the 900C charge threshold. 15 % exceed the 2700C threshold.



## Implications in Blade LPS Design and Service



### Understanding the risk

- Risk assessment is already part of IEC 61400-24.
- Understanding the expected exposure of existing or future sites is a first steps towards:
  - Lightning protection considerations.
  - Lightning monitoring needs.
  - Scheduling onsite operations and maintenance.





#### Taking control over lightning attachment



Second side receptor Inline type Third side receptor Branch type

Polytech

Wind for life™

14



#### **LPS Inspection and Service**

- Link to IEC 61400-24 and IEC 61400-32
- The maintenance of the LPS is fully connected to the exposure and the wear of the different components.







- How to schedule inspections/service?
- Lightning exposure is site specific.
- Basing the inspections on a calendar can be risky: a receptor that looks good today can be completely worn out in a couple of weeks and still may need to survive a couple of years until the next inspection.
- The examples presented from the sites monitored clearly show that a threshold of accumulated charge can be exceeded in just a couple of strikes.



#### The challenge with inspections

- Inspections focus many times on the outside of the blade.
- It is difficult to assess the condition of internal components and connections of the LPS.
- Even internal inspections may not be accurate in the sense that it is difficult to judge whether a connection is about to become loose or is even broken.
- Continuity measurements only work if there is a full disconnection of a simple LPS system, i.e. the down conductor is disconnected from the tip receptor or a receptor block. Equipotential bond





Low resistance - measurement shows everything is OK.

## **Condition monitoring of the LPS**



#### Fundamental idea:

- Injection of a signal into a blade and determine the status of the LPS by analyzing the response of the signal.
- Status of the LPS can be evaluated during idle times or at specific load points.
- Cross-comparison of many samples to evaluate if changes to LPS happened.

#### **Expected LPS signature performance**

- Continuous monitoring of the LPS integrity of GFRP and CFRP blades
- ✓ Single or multiple down conductors
- Detection of:
  - Disconnected conductors
  - Disconnected bonds to Mesh or CFRP
  - ✓ Missing Solid metal tips >= 50cm
- Provide a warning signal if something has happened
- ✓ Provide a damage location
- ✓ Resistive changes LPS >  $5\Omega$



#### **360° Lightning Protection**



## Thank you

jal@polytech.com

